Search Notes



Application/Control No.	Applicant(s)/Patent Under Reexamination
10677075	KONNO, TAKESHI
Examiner	Art Unit
Nam V Nguyen	2612

SEARCHED			
Class	Subclass	Date	Examiner
340	5.61; 5.32; 5.33; 825.36; 825.49; 426.11	3/20/09	NN

SEARCH NOTES		
Search Notes	Date	Examiner
Search EAST: USPAT; US-PUB; EPO; JPO; and Derwent. (updated search).	3/20/09	NN
Search Terms: warning light/lamp/indicator with failed to detect; not received signal; detached; lost; out of range; disconnect with receiver.	3/20/09	NN

INTERFERENCE SEARCH			
Class	Subclass	Date	Examiner

/N. V. N./ Examiner.Art Unit 2612	

U.S. Patent and Trademark Office Part of Paper No.: 20090320